



Photo 5



Photo 7



Photo 8




Photo 6



		2021 Back River Geotechnical Inspection		
		Camp Contact Water Pond Footprint		
	Back River Project	Date: Feb 2022	Approved:	Figure: 21



Photo 9 – Some ponded water observed within footprint



Photo 11



Photo 10



Photo 12 – Some ponded water observed within footprint



Photo 13




Photo 15



Photo 16 – Fractured rock extending under CWO embankment area



Photo 14 – Fracture rock extending beyond CWP embankment area



		2021 Back River Geotechnical Inspection		
		Camp Contact Water Pond Footprint		
Job No: 1CS020.021 Filename: BackRiver_2021GeotechInspection_PhotoLog	Back River Project	Date: Feb 2022	Approved: DG / JBK	Figure: 23



Photo 17 – View downstream from road



Photo 18



Photo 19



Photo 20



Job No: 1CS020.021
 Filename: BackRiver_2021GeotechInspection_PhotoLog



Back River Project

2021 Back River Geotechnical Inspection

**Camp Contact Water Pond
 Footprint**

Date: Feb 2022	Approved: DG / JBK	Figure: 24
-------------------	-----------------------	----------------------



Photo 21



Photo 22




Photo 23 – Note cracks on roadway, road fill ~4 m above tundra

 Job No: 1CS020.021 Filename: BackRiver_2021GeotechInspection_PhotoLog	 Back River Project	2021 Back River Geotechnical Inspection		
		Camp Contact Water Pond Footprint		
		Date: Feb 2022	Approved: DG / JBK	Figure: 25



Photo 24



Photo 25

		2021 Back River Geotechnical Inspection		
		Camp Contact Water Pond Footprint		
Job No: 1CS020.021 Filename: BackRiver_2021GeotechInspection_PhotoLog	Back River Project	Date: Feb 2022	Approved: DG / JBK	Figure: 26



Photo 26 – Highly fracture rock outcrop




Photo 27 – Highly fractured rock outcrop extending through planned embankment area

		2021 Back River Geotechnical Inspection		
		Camp Contact Water Pond Footprint		
Job No: 1CS020.021 Filename: BackRiver_2021GeotechInspection_PhotoLog	Back River Project	Date: Feb 2022	Approved: DG / JBK	Figure: 27



Photo 28




Photo 30



Photo 29




Photo 31

		2021 Back River Geotechnical Inspection		
		Camp Contact Water Pond Footprint		
Job No: 1CS020.021 Filename: BackRiver_2021GeotechInspection_PhotoLog	Back River Project	Date: Feb 2022	Approved: DG / JBK	Figure: 28



Note: At the time of the summer SRK inspection there were no tanks installed on site at the plant site pad. This photo shows an overview of the site development activities at the plant site pad area at the time of the summer 2021 inspection. This location was in a state of active development

		2021 Back River Geotechnical Inspection			
Job No: 1CS020.021 Filename: BackRiver_2021GeotechInspection_PhotoLog		Back River Project		Site Development Activist at the Plant Pad / Site	
			Date: Feb 2022	Approved: DG / JBK	Figure: 28

