



Photo 39. CV-224 downstream, silt fence replaced.



Photo 40. BG-01 upstream, silt fence in disrepair.





Photo 41. BG-01 upstream, silt fence replaced.




Photo 42. CV-186 upstream, silt fence along south bank in disrepair.





**Photo 43.** CV-186 upstream, silt fence along south bank replaced.



**Photo 44.** CV-186 water pooling on roadway near culvert crossing.





**Photo 45.** CV-186 downstream, rock armouring of roadside berm.



**Photo 46.** CV-187 upstream, turbid water approximately 140 m upstream of CV-187 due to rain event.



**Photo 47.** CV-187 upstream, spring berms installed approximately 140 m upstream of CV-187 due to rain event.