



Itivia Bypass Road/Culvert - Photo 49: Culvert C17 outlet.




Itivia Bypass Road/Culvert - Photo 50: Culvert C18 inlet.




Itivia Bypass Road/Culvert - Photo 51: Culvert C18 inlet.

Itivia Bypass Road/Culvert - Photo 52: Culvert C18 outlet.





Itivia Bypass Road/Culvert - Photo 53: Culvert C19 inlet.



Itivia Bypass Road/Culvert - Photo 54: Culvert C19 inlet.



Itivia Bypass Road/Culvert - Photo 55: Culvert C19 outlet.



Itivia Fuel Tankfarm - Photo 56:

Ponded water observed in Tankfarm



Itivia Fuel Tankfarm - Photo 57:

Tankfarm overview, looking east

West Elevation

📍 111°E (T) 📍 62°48'5"N, 92°5'57"W ±25m ▲ -3m



Itivia Fuel Tankfarm - Photo 58:

Tankfarm side berm and foundation




📍 353°N (T) 📍 62°48'1"N, 92°5'52"W ±4m ▲ 4m



Itivia Fuel Tankfarm - Photo 59:

Tankfarm side berm and water ponding



Itivia Fuel Tankfarm - Photo 60:

Tankfarm side berm and foundation