

Kangiqliniq H.T.O.

ᑲᑦᑭᑦᑭᑦᑭᑦ ᑲᑦᑭᑦᑭᑦᑭᑦ ᑲᑦᑭᑦᑭᑦᑭᑦ

P.O. Box 194

ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦ 194

Rankin Inlet, Nunavut X0C 0G0

ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦ, ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦ X0C 0G0

FAX Memo

ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦ ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦ

Date ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦ

July 03, 2008.



Phone ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦ 867-645-2350 / Fax ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦ 867-645-3257 / Email ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦ rankinhcto@qiniq.com

Urgent ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦ

Review ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦ

Reply ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦ

To

ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦ

Leslie Payette

From

ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦ

Norman W. Ford.

Comments ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦ

Late but we are catching up.

Pages ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦ 3. Fax ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦ 867-983-2594

President

ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦ

Matthew Innuksuk

Vice President

ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦ

Jack Kabvitok

Secretary Treasurer

ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦ

Cedric Autut

Manager:

ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦ

Naaman W Ford

If this is sent in error please discard: ᑲᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦᑭᑦ

## COMMENT FORM FOR NIRB SCREENINGS

The Nunavut Impact Review Board (NIRB) has a mandate to protect the integrity of the ecosystem for the existing and future residents of Nunavut. To assess the environmental and socio-economic impacts of the project proposal, NIRB would like to hear your concerns, comments and suggestions about the following project proposal application:

Project Proposal Title: Rankin Inlet Fuel Facility Upgrade - Land farm	
Proponent: Community & Government Services, Government of Nunavut	
Location: Hamlet of Rankin Inlet, Nunavut	
Comments Due By: May 7, 2008	NIRB #: 08UN039

Indicate your concerns about the project proposal below:

<input type="checkbox"/> no concerns	<input checked="" type="checkbox"/> traditional uses of land
<input type="checkbox"/> water quality	<input type="checkbox"/> Inuit harvesting activities
<input type="checkbox"/> terrain	<input type="checkbox"/> community involvement and consultation
<input type="checkbox"/> air quality	<input type="checkbox"/> local development in the area
<input type="checkbox"/> wildlife and their habitat	<input type="checkbox"/> tourism in the area
<input type="checkbox"/> marine mammals and their habitat	<input type="checkbox"/> human health issues
<input type="checkbox"/> birds and their habitat	<input type="checkbox"/> other: _____
<input type="checkbox"/> fish and their habitat	_____
<input type="checkbox"/> heritage resources in area	_____

Please describe the concerns indicated above:

there is a (beavarder) A big rock that has been used for spotting from on top of the hill. That is also adjacent to the

Do you have any suggestions or recommendations for this application?

tank farm. the Board would want to know if it is in the upgrade side. They would like to know if it is in

Do you support the project proposal? Yes ☐ No ☐ Any additional comments?

the site and would like to get a site relocated far spotting from of the Tank farm removes this beavarder (BIG. ROCK).

Name of person commenting: Matthew Innuish of Rankin Inlet

Position: President Organization: RI H2O

Signature: M. Innuish Date: May 14, 2008

6<sup>th</sup> Dec, 1960 XOC OGO



Matthew Innukshuk  
President KHTO