

NWB Annual Report

Year being reported: 2016

License No: 3BC-NET1520

Issued Date: July 27, 2015

Expiry Date: July 26, 2020

Project Name: CWS Nikko Island Goose Research Camp

Licensee: Canadian Wildlife Service

Mailing Address: Environment and Climate Change Canada
Suite 150-123 Main Street
Winnipeg, MB. R3C 4W2

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B Item 1

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Nettilling Lake	
Water Quantity:	5 cu. m/day	Quantity Allowable Domestic (cu.m)
	0.07 cu. m/day	Actual Quantity Used Domestic (cu.m)
	n/a	Quantity Allowable Drilling (cu.m)
	n/a	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☒ Solid Waste Disposal
- ☐ Sewage
- ☐ Drill Waste
- ☐ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

Incinerator has been installed on site for Household Waste.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)
 Date of Spill:
 Date of Notification to an Inspector:
 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed ▼

Additional Details:

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed ▼

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Progressive reclamation as requested by the inspector has been ongoing during the life of the permit. An incinerator has been installed on-site for disposal of combustible household waste. Non-combustible material has been removed on an annual basis for disposal and recycling

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below ▼

Additional Details:

Details outlined in Spill contingency plan on file.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A) ▼

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

--

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

--

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

--

Any additional comments or information for the Board to consider

--

Date Submitted:

October 19, 2016

Submitted/Prepared by:

Jim Leafloor

Contact Information:

Tel: 204-983-5265

Fax: 204-983-5248

email: jim.leafloor@canada.ca