

APPENDIX F

Regulatory Inspections



LAND USE PERMIT INSPECTION FORM

☒ Original
☐ Follow-Up Report

| | |
|--|---|
| Authorization Holder | Authorization Holder Representative |
| Latitude Uranium | Philo Schoeman |
| Authorization No. / Expiry | Representative's Title |
| N2019C0013/July 31, 2026 | Camp Manager |
| Other Authorization No. / Expiry | |
| 2BE-ANG2227/April 11, 2027 | |
| Date of Inspection | Inspector |
| July 14, 2024 | RMO Kyle Amsel |
| Activities Inspected | |
| <input checked="" type="checkbox"/> Camp <input type="checkbox"/> Roads/Hauling | <input type="checkbox"/> Drilling <input type="checkbox"/> Other: Exploration |
| <input type="checkbox"/> Mining | <input checked="" type="checkbox"/> Construction <input type="checkbox"/> Other: |
| | <input type="checkbox"/> Reclamation |
| | <input checked="" type="checkbox"/> Fuel Storage |

| | | | |
|--|--|--|---|
| SECTION 1 | <input checked="" type="checkbox"/> Comments (s. __) | <input type="checkbox"/> Non-Compliance with Act or Licence (s. __) | <input type="checkbox"/> Action Required (s. __) |
| <p>On July 14, 2024 Resource Management Officer Kyle Amsel (Inspector) for Crown-Indigenous Relations and Northern Affairs Canada (CIRNAC) conducted an Inspection of Land Use Permit N2019C0013 (Permit) issued to Latitude Uranium (Permittee).</p> <p>Preliminary Information</p> <p>The purpose of this inspection was to ensure compliance with conditions of the Permit. The Exploration Project has it's camp located on Crown Land while the drilling area is both on Inuit-Owned Land and Crown Land.</p> <p>Observations</p> <ol style="list-style-type: none">The Camp is generally located at N62° 34' 15.0" W98° 27' 19.0".The camp is situated on sand/gravel eskers and is divided in three portions. Accommodations, kitchen, core shack, washrooms and dry are located on one esker. Helicopter pad, fuel storage, equipment storage and core storage is located on another esker within 150m of accommodations area and connected by small trail through a swampy area. A landing strip is located on an esker approximately 1km to the West and not connected by any ground trail.Fuel on site is stored in large covered berms and appears clean and well kept.Waste<ol style="list-style-type: none">The grey water sump is located at N62° 34' 45.1" W98° 27' 19.1".The camp utilizes pacto toilettes which are incinerated.Enclosed garbage bins are located outside the kitchen. This garbage is backhauled.Temp Camp located at N62° 31' 15.2" W99° 08' 15.1"<ol style="list-style-type: none">The area was inspected and no remnants were located of the camp.Drilling<ol style="list-style-type: none">The drilling for this season was located on Inuit-Owned Lands. However in previous seasons the YAT and Dipole areas were drilled. These areas were inspected and nothing of note was located. <p>Administrative</p> <p>The 2023 annual report was submitted.</p> | | | |
| SECTION 2 | <input type="checkbox"/> Comments (s. __) | <input checked="" type="checkbox"/> Non-Compliance with Act or Licence (s.2) | <input type="checkbox"/> Action Required (s. __) |
| No non-compliance | | | |
| SECTION 3 | <input type="checkbox"/> Comments (s. __) | <input type="checkbox"/> Non-Compliance with Act or Licence, (s. __) | <input checked="" type="checkbox"/> Action Required (s.3) |
| No actions required. | | | |

| | |
|----------------------------|------------------|
| Licensee or Representative | Inspector's Name |
| Cliff Revering | RMO Kyle Amsel |
| Signature | Signature |
| Date | Date |
| October 21, 2024 | October 21, 2024 |

| | | |
|------------------|--|---|
| Office Use Only: | Follow-up report to be issued by Inspector | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
|------------------|--|---|



PHOTO LOG

| Date: | Authorization Number: | Camera/Model: | Inspector |
|---------------|-------------------------------|----------------|-----------|
| July 14, 2024 | N2019C0013 | Sony DSC-HX50V | RMO Amsel |
| Photo No. | Lat/Long (DD.MM.SS.SS, NAD83) | | |
| Photo 1 | N62° 34' 23.1" W98° 27' 34.9" | | |



| Description: |
|-------------------------|
| Lined fuel drum storage |

| Photo No. | Lat/Long (DD.MM.SS.SS, NAD83) |
|-----------|-------------------------------|
| Photo 2 | N62° 34' 31.8" W98° 28' 59.6" |



| Description: |
|----------------------------|
| Landing strip West of Camp |



WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

| | |
|--|---|
| Authorization Holder | Authorization Holder Representative |
| Latitude Uranium | Philo Schoeman |
| Authorization No. / Expiry | Representative's Title |
| 2BE-ANG2227/April 11, 2027 | Camp Manager |
| Other Authorization No. / Expiry | |
| N2019C0013/July 31, 2026 | |
| Date of Inspection | Inspector |
| July 14, 2024 | RMO Kyle Amsel |
| Activities Inspected | |
| <input checked="" type="checkbox"/> Camp <input type="checkbox"/> Roads/Hauling | <input checked="" type="checkbox"/> Drilling <input type="checkbox"/> Other: Exploration |
| <input type="checkbox"/> Mining | <input checked="" type="checkbox"/> Construction <input type="checkbox"/> Other: |
| <input type="checkbox"/> Reclamation | <input checked="" type="checkbox"/> Fuel Storage |

| | | | |
|--|--|--|---|
| SECTION 1 | <input checked="" type="checkbox"/> Comments (s. __) | <input type="checkbox"/> Non-Compliance with Act or Licence (s. __) | <input type="checkbox"/> Action Required (s. __) |
| <p>On July 14, 2024 Resource Management Officer Kyle Amsel (Inspector) for Crown-Indigenous Relations and Northern Affairs Canada (CIRNAC) conducted an Inspection Water Licence 2BE-ANG2227 issued to Latitude Uranium (Licensee).</p> <p>Preliminary Information</p> <p>The purpose of this inspection was to ensure compliance with conditions of the License. The Exploration Project has it's camp located on Crown Land while the drilling area is both on Inuit-Owned Land (IOL) and Crown Land.</p> <p>Observations</p> <ol style="list-style-type: none">The Camp is generally located at N62° 34' 15.0" W98° 27' 19.0".The camp is situated on sand/gravel eskers and is divided in three portions. Accommodations, kitchen, core shack, washrooms and dry are located on one esker. Helicopter pad, fuel storage, equipment storage and core storage is located on another esker within 150m of accommodations area and connected by small trail through a swampy area. A landing strip is located on an esker approximately 1km to the West and not connected by any ground trail.Fuel on site is stored in large covered berms and appears clean and well kept.Waste<ol style="list-style-type: none">The grey water sump is located at N62° 34' 45.1" W98° 27' 19.1".The camp utilizes pacto toilettes which are incinerated.Enclosed garbage bins are located outside the kitchen. This garbage is backhauled.Temp Camp located at N62° 31' 15.2" W99° 08' 15.1"<ol style="list-style-type: none">The area was inspected and no remnants were located of the camp.Drilling<ol style="list-style-type: none">The drilling for this season was located on IOL. However in previous seasons the YAT and DP areas were drilled. These areas were inspected and nothing of note was located.The Inspector attended Drill #2 at N62° 34' 44.72" W98° 34' 3.92" located on IOL. The drill area was noted to be clean with no garbage or debris. A slump occurred at this drill area on the first drill location and the drill was subsequently moved over. Water intake for drill 2 was N62° 34' 42.6" W98° 34' 14.92". A screen was on the water intake and a water meter records water usage. At time of inspection the meter read 7343gal or 27.7m³.There are two cuttings storage areas within the IOL parcel proximal to historic drilling.<ol style="list-style-type: none">Historic hot cuttings or cutting with higher concentrations of Naturally Occurring Radioactive Material (NORM) storage is located in drums and is located near N62° 35' 25.7" W98° 37' 30.2". The licensee has indicated plans to review, consolidate and manage these cuttings which are remnants of the previous owner of the operations. The Inspector notes that these drums are standing upright in an un-bermed area which causes risk to fresh water.Historic cold cuttings with low or no levels of NORM are stored near N62° 34' 21.3" W98° 30' 41.3". These cuttings, also remnants of the previous camp owners are stored in mega bags. <p>Administrative</p> <p>The 2023 annual report was submitted.</p> | | | |
| SECTION 2 | <input type="checkbox"/> Comments (s. __) | <input checked="" type="checkbox"/> Non-Compliance with Act or Licence (s.2) | <input type="checkbox"/> Action Required (s. __) |
| No non-compliance | | | |
| SECTION 3 | <input type="checkbox"/> Comments (s. __) | <input type="checkbox"/> Non-Compliance with Act or Licence, (s. __) | <input checked="" type="checkbox"/> Action Required (s.3) |
| The Licensee shall: - Take necessary steps to prevent impacts to water from the hot core storage area | | | |

| | |
|----------------------------|------------------|
| Licensee or Representative | Inspector's Name |
| Cliff Revering | RMO Kyle Amsel |
| Signature | Signature |
| Date | Date |
| October 21, 2024 | October 21, 2024 |

| | | |
|------------------|--|---|
| Office Use Only: | Follow-up report to be issued by Inspector | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
|------------------|--|---|



PHOTO LOG

| | | | |
|------------------------|-------------------------------------|---------------------------------|------------------------|
| Date: July 14, 2024 | Authorization Number: N2019C0013 | Camera/Model: Sony DSC-HX50V | Inspector RMO Amsel |
| Photo No. | Lat/Long (DD.MM.SS.SS, NAD83) | | |
| Photo 1 | N62° 34' 23.1" W98° 27' 34.9" | | |



| |
|-------------------------|
| Description: |
| Lined fuel drum storage |

| | |
|-----------|-------------------------------|
| Photo No. | Lat/Long (DD.MM.SS.SS, NAD83) |
| Photo 2 | N62° 34' 31.8" W98° 28' 59.6" |



| |
|----------------------------|
| Description: |
| Landing strip West of Camp |



| Photo No. | Lat/Long (DD.MM.SS.SS, NAD83) |
|-----------|-------------------------------|
| Photo 3 | N62° 34' 42.9" W98° 34' 25.6" |



| Description: |
|--------------|
| Drill #2 |

| Photo No. | Lat/Long (DD.MM.SS.SS, NAD83) |
|-----------|-------------------------------|
| Photo 4 | N62° 35' 25.7" W98° 37' 30.2" |



| Description: |
|---------------------------------|
| Historical hot cuttings storage |