

NWB Annual Report

Year being reported:

2023

License No: 2BE-HRP1932

Issued Date: June 9, 2022

Expiry Date: June 8, 2032

Project Name: Ulu Gold Project

Licensee: Blue Star Gold Corp.

Mailing Address:

500-700 W. Pender St.
Vancouver, BC
V6C 1G8

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Tara Gunson, APEX Gescience Ltd., on behalf of Blue Star Gold Corp.

General Background Information on the Project (*optional):

The Ulu Gold Project is comprised of the Crown-granted Ulu Mining Lease, L-3563, and the Hood River Mineral Exploration Agreement held with NTI (HoodRiver-0010. Both components of the Ulu Gold Project surface rights are regulated by the Kitikmeot Inuit Association (KIA). The Roma Project is located approximately 40 km north of the Ulu Gold Project in the High Lake Greenstone Belt. The Roma Project comprises Crown claims and a Mineral Exploration Agreement with NTI, which covers approximately 14,000 ha.

Surface activities are licenced by the Kitikmeot Inuit Association (KIA) under one licence, while there is one water licence for Hood River and Roma activities (2BE-HRP1924) and a separate water license for Ulu (2BM-ULU2030).

No water was used or waste disposed under licence 2BE-HRP1924 in 2023.

Licence Requirements: the licensee must provide the following information in accordance with

Part C

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	West Lake (domestic)	
Water Quantity:	0 m3/day	Quantity Allowable Domestic (cu.m)
	0 m3/day	Actual Quantity Used Domestic (cu.m)
	299 m3/day	Quantity Allowable Drilling (cu.m)
	0 m3/day	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☐ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:

Additional Details:

All of Blue Star's activities were based out of the Ulu camp in 2023 under license 2BM-ULU2030 and therefore will be reported in the Annual Report Form for licence 2BM-ULU2030.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No spills were recorded in 2023

Revisions to the Spill Contingency Plan

Other: (see additional details) ▼

Additional Details:

The Spill contingency Plan was been updated to include the two new claims staked at the Roma Project in 2023.

Revisions to the Abandonment and Restoration Plan

Other: (see additional details) ▼

Additional Details:

The Abandonment and Restoration Plan was been updated to include the two new claims staked at the Roma Project in 2023.

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

No work was undertaken in 2023 under licence 2BE-HRP1924. All 2023 reclamation work relates to 2BM-ULU2030 and will be reported in that annual Reporting form.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A) ▼

Additional Details:

No water sources were used under licence 2BE-HRP1932 in 2023.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A)

Additional Details:

No waste was deposited under licence 2BE-HRP1932 in 2023.

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

N/A

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

N/A

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC

Additional Details: (Dates of Report, Follow-up by the Licensee)

N/A

Any additional comments or information for the Board to consider

Date Submitted:

March 31, 2024

Submitted/Prepared by:

Tara Gunson

Contact Information:

Tel: 780-467-3532

Fax:

email: tgunson@apexgeoscience.com

GPS Coordinates for water sources utilized

Source Description	Latitude			Longitude		
	°	Deg	Min	°	Deg	Min

GPS Locations of areas of waste disposal

Location Description (type)	Latitude			Longitude		
	°	Deg	Min	°	Deg	Min