



2BE-HAK0915 Water Licence Inspection April 23-24 2013

Photos from Inspection



Figure 1. Hackett Camp and Airstrip April 23, 2013



Figure 2. New water metering system.



Figure 3. Backlog at incinerator.

Week	Date	Pacho Bags	Pacho Lbs	Kitchen lbs	Dillers lbs	Office/Dry lbs	Incinerator Operator	Comments
8	Monday, April 08, 2013							
8	Tuesday, April 09, 2013							
8	Wednesday, April 10, 2013							
8	Thursday, April 11, 2013							
8	Friday, April 12, 2013							
8	Saturday, April 13, 2013							
8	Sunday, April 14, 2013							
9	Monday, April 15, 2013							
9	Tuesday, April 16, 2013							
9	Wednesday, April 17, 2013							
9	Thursday, April 18, 2013	9	10	40	75	5		
9	Friday, April 19, 2013	9	15	60	57	8		
9	Saturday, April 20, 2013	9	10	55	65	4		
10	Sunday, April 21, 2013	8	17	75	50	7		
10	Monday, April 22, 2013	9	15	70	50	5		
10	Tuesday, April 23, 2013							
10	Wednesday, April 24, 2013							
10	Thursday, April 25, 2013							
10	Friday, April 26, 2013							
10	Saturday, April 27, 2013							
10	Sunday, April 28, 2013							
	Monday, April 29, 2013							

Figure 4. Partially completed logs.



Figure 5. New water recirculation system implemented in 2013.



Figure 6. Mega-bag of sludge, weeping saline drill water. Must be contained, particularly on ice.



Figure 7. Warm and well-organized drill shack. Muds and oils all in a spill tray, bags for sorting garbage hanging on wall.



Figure 8. Areas of fuel (red circles) and salt (yellow circle). The rest is mostly drill and construction materials.



Figure 9. Tidy tank balanced on a small spill tray; does not provide room for the hose and nozzle etc.




Figure 10. Barrels on heli-pad. Pump left in and spills visible. Liner under heli-pad recommended to minimize cleanup necessary in the future.