Jericho Diamond Mine Project
Uyagakhiuktit Havaangit

- Approximately 240km SE of Kugluktuk / Haniani 240 km-nik ungahiaqtuq hivuraanit kivalliqhianit Qurluqtum
- Single Open Pit Mine / Avaliittuq Hauyauyuq Uyaraghiuqvik
- Processing Facility / Amiqhaiqarviuyuq
- Processed kimberlite containment areas / Hiqupluqtiqhimayut kimberlite-mik tutquumaviat
- Camp and Supporting Buildings / Hiniktarviat Atuqtauyullu Ikluqpait
- Fuel Tank Farm / Urhuqyuaqarvingit
- Airstrip / Milvinga
- Roads connecting infrastructure / Apqutit atatapkaiyut ikluqpangnik

Site History

- July 2004 – NIRB issued Project Certificate 002 to Tahera Corporation Ltd.
- January 2005 – Project Certificate 002 transferred to Benachee Resources Inc,
- August 2010 – Shear Diamonds (Nunavut) Corp purchased Jericho
- August 2011 - NIRB transferred Project Certificate 002 to Shear
- October 2012 – Site placed in temporary closure by Shear
- January 2014 – AANDC declared site abandoned and assumed control of site
- September 2016 – NIRB screened INAC's "Jericho Mine Site Stabilization Project"
  - Majority of work completed summer 2017
  - Small amount of work to be completed summer 2018
- NIRB Site Visit June 2018

Initurlinga Qanuritpa

- July 2004 – Tahapkuat NIRB tunihimayut Havakhautikhanik Naunaitkutak Atugakhanik Nungudjutilingnik Ubluinik Nunguumaanut Atuknianut Naunnaitkutak 002 tahapkununga Tahera Katimayit.
- January 2005 – Havaaghanut Titirautit 002 nuutitauyut talvunga Benachee Resources Inc-kunnut
- August 2010 – Shear Diamonds (Nunavunmi) Kuapuriissat niuviqtaat Jericho-kut
- August 2011 – NIRB-kut nuutittiyaat Havaaghanut Titirautit 002 talvunga Shear-kunnut
- October 2012 – Havakvik umiktikaffuktauhimayuq Shear-kunnit
- January 2014 – AANDC qimaktauyuliqutigiyaat havakvik munaliqhugulu
- September 2016 – NIRB-kut ihivriuqhimayait INAC-kut "Jericho Uyaraghiuqvianik Aulapkaittiarniqmut Havaaghainik"
    - Amihut havaangit iniqtauhimayut auyami 2017-mi
    - Ikittut havaaghait iniqtauyughat huli auyami 2018-mi
- NIRB-kut pulaaqhimayait Havakviat June 2018-mi

Course kimberlite cover on processed kimberlite tailings

Hiqupluqhimayunik kimberlite-mik qaanganunngaqhivaktut hiqupluqtiqpaalliqhimayunik kimberlite-nik



Fuel Tanks - Cleaned and Emptied, Contaminated soil - liner, berm, and capped

Uqhughat Qataryuit – Halummaqtiqhimayut imaiyaqtauplutiklu, Kuviviuhimayuq nuna – hittiriipkuhiqtiqhimayuq, kingighilaaqhimayullu, matuliqtauplutiklu

Breach of Divider Dyke A and West Dam to allow for natural water flow

Ahikkuuqtittiyut Aviktuqviat Dyke A Uataanilu Haputiliuqhimayuq imaq qurluriami



Removal of C1 Diversion Ditch
Breach of Pit Wall to re-route water into Open Pit
Outflow from pit lake into Carat Lake

Ahivaiyut taapkuninnga C1 Ahikkuuqviat Hauyauhimayuq
Ahikkuuqtittiyut Taluanik ahikkuuqtittiyaamik imaqmik Angmaumayumut Uyaraghiuqvingmut
Anialattiyut uyaraghiuqviup tahiraanit talvunga Carat Tahianut