

NWB Annual Report

Year being reported: 2013 ▼

License No: 2BE-STO1015 **Issued Date:** November 3, 2010
Expiry Date: July 31, 2015

Project Name: STORM

Licensee: COMMANDER RESOURCES LTD

Mailing Address:
 SUITE 1100, 1111 MELVILLE STREET
 VANCOUVER, BC V6E 3V6

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

APEX GEOSCIENCE LTD - APPROVED CONSULTANT WORKING ON THE STORM PROJECT FOR COMMANDER RESOURCES LTD

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 2 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

| | | |
|------------------|-----|--------------------------------------|
| Water Source(s): | N/A | |
| Water Quantity: | 2 | Quantity Allowable Domestic (cu.m) |
| | 0 | Actual Quantity Used Domestic (cu.m) |
| | 15 | Quantity Allowable Drilling (cu.m) |
| | 0 | Total Quantity Used Drilling (cu.m) |

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☐ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:

Additional Details:

NO WATER USED - No drilling or camp construction undertaken in 2013.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

Additional Details:

Revisions to the Abandonment and Restoration Plan

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

An inspection was conducted in July 2013, however no inspection report has been received.

Any additional comments or information for the Board to consider

No water was used and no waste water was created during the 2013 field season. 2013 field work was limited to re-sampling of historic drill core and surface rock sampling. No camp was constructed on the property. The field crew was based out of Arctic Watch Lodge, located approximately 50 km north of the Storm Property.

Date Submitted:

February 5, 2014

Submitted/Prepared by:

Christopher Livingstone

Contact Information:

Tel: 604-696-9628

Fax: 604-681-8775

email: clivingstone@apexgeoscience.com